

FIG. 1

FIG. 2




FIG. 3(a)

NORMALLY FABRICATED PATTERN





FIG. 3(b)

PATTERN HAVING A DEFECT



A : ISOLATED DEFECT
B : PROTRUSION
C : SHORT
D : OMISSION

E : DISCONNECTION
F : THIN FILM RESIDUAL
G : BAD APERTURE

FIG. 4




FIG. 5





FIG. 6






FIG. 7(a)




FIG. 7(b)




FIG. 8

FIG. 9(a)




FIG. 9(b)




FIG. 9(c)




FIG. 10




FIG. 11




FIG. 12




FIG. 13

